



BEFORE AND AFTER ON BARKERS ROAD AROUND TREE LISTED FOR FELLING



Original Amey assessment: Kerbstone absent, f/w mounded, cannot repair without unacceptable root damage

Pavement repair: Half profile kerb stone used.

